



Release notes GLB/TWIN firmware version 1.2.4

- Version 1.2.4 – Common firmware for GLB and TWIN wallboxes

1. Added features

- 1.1. Dip-switches SW1/SW2 configuration visible in HMI
- 1.2. DLM energymeter Ampere (A) values are now reported with one decimal
- 1.3. Automatic summer/winter time change, internal clock
- 1.4. SSID from wallbox show "GARO_STARTING_WAIT" until wifi module is ready. Previous versions showed SSID "GLB898989898" at startup.

2. Performance improvements and bug fixes

- 2.1. Bug fix – Internal clock setting sets seconds correctly
- 2.2. Bug fix - Invisible SSID at startup, correction to make sure that AP mode is active at startup