

Release notes GLB/TWIN firmware version 1.2.3

- Version 1.2.3 – Common firmware for GLB and TWIN wallboxes

1. Added features and

- 1.1. Added new models in product table (only for production purpose)

2. Performance improvements and bug fixes

- 2.1. Improved HMI functionality with older PCB firmware (version 2.xx)
- 2.2. Improved RealTimeClock(RTC) for synchronization of HMI clock
- 2.3. Improved firmware update function for TWIN boxes
- 2.4. Improved Top-LED and HMI indication for DC-fault/DC hardware error
- 2.5. Improved HMI response time for 'Identify' function
- 2.6. Bug fix – Energy meter values correction in HMI with older PCB firmware (version 2.xx)
- 2.7. Bug fix – Old incorrect registered energy meter values are sorted out from history database
- 2.8. Bug fix – SW3(factory reset) will now disable/reset RFID, cable-lock settings and set lowest charging current to 6A