

Release notes GLB firmware version 1.3.7

- Version 1.3.7 support both GLB and TWIN wallboxes

1. Bug fixes

- 1.1. Problem that GLB versions w/o built in DC-fault detection indicate DC-fault solved
- 1.2. Problem that inactivated TWIN slavebox won't be activated by factory reset solved